

FIG. 1







FIG. 2










FIG. 3B






FIG. 3C












FIG. 4






FIG. 5
















FIG. 8





FIG. 9








FIG. 11






FIG. 12






FIG. 13A




FIG. 13B




FIG. 13C




FIG. 13D






FIG. 14

WORN-OUT GAP (mm)




FIG. 15A 42 43 60






FIG. 16




FIG. 17




FIG. 18A FIG. 18B FIG. 18C FIG. 18D FIG. 18E











FIG. 19A PRIOR ART




FIG. 19B PRIOR ART




FIG. 20 PRIOR ART

